

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N165TW

DIRECTIVE NUMBER AMENDMENT EFFECTIVE DATE	REVISION LOCATION	DESCRIPTION	VENDOR		COMPLIANCE	NEXT DUE
			METHOD			
AD 2000-01-09		TO PREVENT THE USE OF UNAPPROVED PARTS	GENERAL ELECTRIC		DATE: 5/08/2000 TIME: 6922.7 LD/CY:	DATE: TIME: LD/CY:
2/11/2000	LH		N/A TO PARTS INSTALLED			
AD 2000-01-09		TO PREVENT THE USE OF UNAPPROVED PARTS	GENERAL ELECTRIC		DATE: 1/14/2000 TIME: LD/CY:	DATE: TIME: LD/CY:
2/11/2000	RH		N/A BY PART SERIAL NUMBER			
AD 2000-05-20		TO ENSURE THAT PROPER PLASTIC BAGS OF THE PASSENGER OXYGEN MASKS ARE INSTALLED AND FUNCTIONING PROPERLY	DASSAULT AVIATION		DATE: 3/21/2000 TIME: 9981.8 LD/CY: 6906	DATE: TIME: LD/CY:
4/18/2000			N/A EQUIPMENT NOT INSTALLED			
AD 2000-11-03		TO PROVIDE THE FLIGHT CREW WITH SPEED LIMITATIONS, WHICH ARE INTENDED TO MITIGATE SEVERE PITCH OSCILLATIONS	DASSAULT AVIATION		DATE: 6/19/2000 TIME: 10288.0 LD/CY:	DATE: TIME: LD/CY:
6/16/2000			AFM REVISION			
AD 2000-12-15		TO PREVENT FAILURE OF THE OVERWING EMERGENCY EXITS TO OPEN & CONSEQUENT INJURY TO PASSENGERS	DASSAULT AVIATION		DATE: 8/15/2007 TIME: 15886.6 LD/CY:	DATE: TIME: LD/CY:
7/20/2000			INSPECT			
AD 2000-12-15		TO PREVENT FAILURE OF THE OVERWING EMERGENCY EXITS TO OPEN & CONSEQUENT INJURY TO PASSENGERS	DASSAULT AVIATION		DATE: 8/03/2000 TIME: 10493.4 LD/CY:	DATE: TIME: LD/CY:
7/20/2000			INSPECT			
AD 2000-18-04		INSPECTION OF SEAT CENTER CROSSMEMBER FOR CRACKS; P/N DM03437-1	AVIANTERiors		DATE: 10/26/2000 TIME: 10768.2 LD/CY: 7515	DATE: TIME: LD/CY:
8/30/2000			N/A EQUIPMENT NOT INSTALLED			
AD 2004-08-15		INSPECT & MODIFY TAWS8000 TO PREVENT THE LOADING OF THE BARO SET POTENTIOMETER SUPERSEDEDS AD 2003-13-08	GOODRICH AVIONICS SYSTEMS		DATE: 5/20/2004 TIME: 13463.3 LD/CY: 9629	DATE: TIME: LD/CY:
6/07/2004			N/A EQUIPMENT NOT INSTALLED			
AD 2004-08-16		MODIFY NARCO AT150 TRANSPONDERS TO PREVENT NOT RESPONDING & RECOGNIZING S MODE INTERROGATIONS	NARCO AVIONICS		DATE: 6/01/2004 TIME: LD/CY:	DATE: TIME: LD/CY:
6/01/2004			N/A			
AD 2004-10-15		TO PREVENT INTERROGATING AIRCRAFT FROM POSSIBLY RECEIVING INACCURATE REPLIES FROM GARMIN GTX 330/330D TRANSPONDERS	GARMIN INTERNATIONAL		DATE: 7/09/2004 TIME: LD/CY:	DATE: TIME: LD/CY:
7/09/2004			N/A			
AD 2004-13-20		TO PREVENT THE GPS NAVIGATION UNIT, UNDER CERTAIN CONDITIONS FROM PROVIDING ERRONEOUS CROSS-DEVIATION	GARMIN INTERNATIONAL		DATE: 8/03/2004 TIME: LD/CY:	DATE: TIME: LD/CY:
8/03/2004			N/A			
AD 2004-16-14		TO PREVENT THE TR/RA VSI-TGAS INDICATOR FROM DISPLAYING "RA FAIL" MESSAGE DURING MULTI-AIRCRAFT ENCOUNTER SOFTWARE UPDATE	THALES AVIONICS		DATE: 9/01/2004 TIME: LD/CY:	DATE: TIME: LD/CY:
9/13/2004			N/A			
AD 2004-16-14		TO PREVENT THE TR/RA VSI-TGAS INDICATOR FROM DISPLAYING "RA FAIL" MESSAGE DURING MULTI-AIRCRAFT ENCOUNTER	THALES AVIONICS		DATE: 9/10/2004 TIME: LD/CY:	DATE: TIME: LD/CY:
9/13/2004			N/A			
AD 2004-19-02		DO A INSPECTION & TEST FOR STRESS CORROSION OF THE WINDOW FRAMES IN THE FLIGHT COMPARTMENT	DASSAULT AVIATION		DATE: 7/29/2005 TIME: 14482.8 LD/CY:	DATE: TIME: LD/CY:
13796						
1025/2004						

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N165TW

DIRECTIVE NUMBER AMENDMENT EFFECTIVE DATE	REVISION LOCATION	D E S C R I P T I O N	V E N D E R		COMPLIANCE	NEXT DUE
			M E T H O D			
AD 2007-26-11		REMOVAL OF INTERTECHNIQUE ALUMINUM PORTABLE OXYGEN CYLINDERS	INTERTECHNIQUE	N/A EQUIPMENT NOT INSTALLED	DATE: 1/28/2008 TIME: 16118.3 LD/CY:	DATE: TIME: LD/CY:
AD 2008-04-14		TO PREVENT FAILURE OF THE OVERWING EMERGENCY EXITS TO OPEN & CONSEQUENT INJURY TO PASSENGERS	DASSAULT AVIATION		DATE: 8/30/2007 TIME: 16162.2 LD/CY:	DATE: TIME: LD/CY:
AD 2008-04-14		TO PREVENT FAILURE OF THE OVERWING EMERGENCY EXITS TO OPEN & CONSEQUENT INJURY TO PASSENGERS	DASSAULT AVIATION	INSPECT	DATE: 9/06/2008 TIME: 16246.7 LD/CY:	DATE: 9/06/2010 TIME: LD/CY:
AD 2008-05-07		VERIFY THE CORRECT ASSEMBLY OF THE ELEVATOR BELLCRANK P/N MY20273-17 OR MY20273-17-15 AT FRAME 26	DASSAULT AVIATION		DATE: 9/06/2008 TIME: 16246.7 LD/CY:	DATE: TIME: LD/CY:
AD 67-07-02 a		TO PREVENT INFLIGHT JAMMING OF THE HORIZONTAL STABILIZER ACTUATOR P/N 21-59-0 OR 21-59-1-A	DASSAULT AVIATION		DATE: 6/21/1967 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 67-27-01		TO PREVENT JAMMING OF THE ENGINE POWER LEVER	DASSAULT AVIATION		DATE: 1/11/1968 TIME: 275.9 LD/CY:	DATE: TIME: LD/CY:
AD 67-27-02 a		TO DETECT & PREVENT CORROSION OF THE WING TO FUSELAGE ATTACHMENT BOLTS	DASSAULT AVIATION		DATE: 6/19/1975 TIME: 2942.9 LD/CY:	DATE: TIME: LD/CY:
10/09/1967			CMW SB 211		DATE: 1/11/1968 TIME: 275.9 LD/CY:	DATE: TIME: LD/CY:
AD 68-03-05		TO DETECT & PREVENT BINDING OF THE AUX HYDRAULIC SYSTEM SELECTOR VALVE CONTROL CABLES	DASSAULT AVIATION		DATE: 1/11/1968 TIME: 275.9 LD/CY:	DATE: TIME: LD/CY:
2/13/1968			CMW SB 0331		DATE: 6/12/1968 TIME: 423.5 LD/CY:	DATE: TIME: LD/CY:
AD 68-10-01		TO DETECT FUEL LEAKAGE RESULTING FROM A RUPTURE OF THE INTERNAL CORES OF THE JANITOR FUEL HEATER P/N B 19D84	DASSAULT AVIATION		DATE: 6/12/1968 TIME: 423.5 LD/CY:	DATE: TIME: LD/CY:
3/22/1968			CMW SB 0358		DATE: 6/12/1968 TIME: 423.5 LD/CY:	DATE: TIME: LD/CY:
AD 68-20-02		TO PREVENT THE INGRESS OF MOISTURE CAUSING INTERNAL CORROSION IN THE LANDING GEAR SWITCH ASSEMBLY	DASSAULT AVIATION		DATE: 6/12/1968 TIME: 423.5 LD/CY:	DATE: TIME: LD/CY:
10/25/1968			CMW SB 333		DATE: 6/06/1969 TIME: 901.7 LD/CY:	DATE: TIME: LD/CY:
AD 69-02-03		TO PREVENT POSSIBLE HAZARDOUS IN FLIGHT LOAD FACTORS. APPLIES TO COLLINS AP-103E OR AP-103F AUTOPILOT WITH STC SA1131WE	DASSAULT AVIATION		DATE: 6/06/1969 TIME: 901.7 LD/CY:	DATE: TIME: LD/CY:
1/25/1969			FOUND P/CMW		DATE: 6/06/1969 TIME: 901.7 LD/CY:	DATE: TIME: LD/CY:
AD 69-11-06		TO PREVENT A POWER LOSS RESULTING FROM DEFECTIVE T2 ASPIRATOR HOSES	DASSAULT AVIATION		DATE: 6/06/1969 TIME: 901.7 LD/CY:	DATE: TIME: LD/CY:
6/02/1969			FOUND P/CMW		DATE: 6/06/1969 TIME: 901.7 LD/CY:	DATE: TIME: LD/CY:
AD 69-22-03		TO PREVENT THE INGRESS OF MOISTURE IN THE LANDING GEAR MICROSWITCH ASSY	DASSAULT AVIATION		DATE: 6/12/1968 TIME: 423.5 LD/CY:	DATE: TIME: LD/CY:
11/26/1969			CMW SB 333		DATE: 6/12/1968 TIME: 423.5 LD/CY:	DATE: TIME: LD/CY:
AD 70-06-07		TO PREVENT A FIRE HAZARD DUE TO CONTINUED OPERATION OF THE APU OIL PUMP MOTOR AFTER APU SHUTDOWN	DASSAULT AVIATION		DATE: 6/12/1968 TIME: 423.5 LD/CY:	DATE: TIME: LD/CY:
4/18/1970			N/A NOT INSTALLED		DATE: 6/12/1968 TIME: 423.5 LD/CY:	DATE: TIME: LD/CY:

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N165TW

DIRECTIVE NUMBER AMENDMENT EFFECTIVE DATE	REVISION LOCATION	D E S C R I P T I O N	V E N D E R M E T H O D	COMPLIANCE	NEXT DUE
AD 70-22-04 (B)		TO DETECT JAMMED CIRCUIT BREAKERS APPLIES TO WOOD CIRCUIT BREAKERS SERIES 105,106,107,108,147,152,254,447,448,2100	WOOD ELECTRIC NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
5/19/1971					
AD 72-19-04 (A)		NICKEL-CADMIUM BATTERIES (TURBINE AC) BATTERIES WITH MORE THAN 50 AMP-HR HAVING POLYSTYRENE CELLS - REPLACE	NICKEL-CADMIUM BATTERIES INSTALLED BATTERY TEMP INDICATOR	DATE: 1/15/1973 TIME: LD/CY:	DATE: TIME: LD/CY:
2/01/1974					
AD 73-15-03 a		TO PREVENT LEAKAGE OF VERY HOT AIR INTO THE REAR COMPARTMENT; PIPE P/N MY20-721-28-1, MY20-721-61-1	DASSAULT AVIATION C/MW SB 0442	DATE: 8/29/1973 TIME: 2412.0 LD/CY:	DATE: TIME: LD/CY:
8/16/1973					
AD 73-23-05		INSPECT FIRST STAGE TURBINE DISCS FOR CRACKS AND A MINIMUM RADIUS IN THE FORWARD AND AFT RABBITT RADIUS	GENERAL ELECTRIC N/A BY ENGINE MODEL	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
11/20/1973	LH				
AD 73-23-05		INSPECT FIRST STAGE TURBINE DISCS FOR CRACKS AND A MINIMUM RADIUS IN THE FORWARD AND AFT RABBITT RADIUS	GENERAL ELECTRIC N/A BY P/N	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
11/20/1973	RH				
AD 73-26-05		TO DETECT CORROSION ON CHEMICAL OXYGEN GENERATORS.	SCOTT AVIATION NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
12/20/1973					
AD 74-08-09		INSPECT LAVATORY WASTE RECEPTACLE: TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS DROPPED IN RECEPT	T-CATEGORY NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
7/29/1998					
AD 74-18-15		EMERGENCY LOCATOR TRANSMITTER LEIGH SYSTEMS - SHARC 7 SERIES	ELT NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
1/23/1975					
AD 74-20-10		SHARC 7 SERIES EMERGENCY LOCATOR TRANSMITTERS EQUIPPED WITH LITHIUM BATTERIES	ELT NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
12/30/1977	R4				
AD 74-24-09 (A)		TO DETECT, CORRECT AND PREVENT TURBINE WHEEL HUB SEPARATION ON AUXILIARY POWER UNITS	GARRETT N/A	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
11/19/1975					
AD 74-24-13		TO PREVENT BEING DEPRIVED OF ALTIMETER READING DURING CERTAIN OPERATING CONDITIONS	UNITED INSTRUMENT WHELEN	DATE: 11/30/1976 TIME: LD/CY:	DATE: TIME: LD/CY:
12/06/1974					
AD 75-05-04		TO PRECLUDE POSSIBLE IGNITION OF FLAMMABLE FLUIDS OR VAPORS; 4427 STROBE FLASH TUBES MANUFACTURED BEFORE 11/01/74	NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
11/01/1974					
AD 75-05-13		TO PRECLUDE POSSIBLE FAILURES OF COMPOUND TURBINE & FAN BLADES. APPLIES TO P/N 6002157P01	GENERAL ELECTRIC C/MW SB A72-124	DATE: 6/03/1996 TIME: 5901.1 LD/CY:	DATE: TIME: LD/CY:
3/03/1976	LH				
AD 75-05-13		TO PRECLUDE POSSIBLE FAILURES OF COMPOUND TURBINE & FAN BLADES. APPLIES TO P/N 6002157P01	GENERAL ELECTRIC C/MW SB A72-124	DATE: 6/13/1975 TIME: 4766.4 LD/CY:	DATE: TIME: LD/CY:
3/03/1976	RH				

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N165TW

DIRECTIVE NUMBER AMENDMENT EFFECTIVE DATE	REVISION LOCATION	D E S C R I P T I O N	V E N D E R M E T H O D	COMPLIANCE	NEXT DUE
AD 75-19-05		TO PREVENT POSSIBLE ACCESSORY DRIVE HORIZONTAL DRIVE SHAFT FAILURE	GENERAL ELECTRIC	DATE: 1/03/1983 TIME: 1957.5 LD/CY:	DATE: TIME: LD/CY:
9/26/1975	LH		N/A		
AD 75-19-05		TO PREVENT POSSIBLE ACCESSORY DRIVE HORIZONTAL DRIVE SHAFT FAILURE	GENERAL ELECTRIC	DATE: 5/09/1977 TIME: 5557.1 LD/CY:	DATE: TIME: LD/CY:
9/26/1975	RH		CW/ SB A72-130		
AD 76-07-09		MODIFY 332C-10 RMI TO PRECLUDE POSSIBLE ERRONEOUS VOR BEARING INFO PRESENTATION, NO FLAG WARN WHEN 26 VAC INPUT PWR LOST	COLLINS	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
4/19/1976			N/A		
AD 76-19-02 d		TO PREVENT POSSIBLE CONTAMINATION OF CABIN VENTILATION AIR WITH FUEL FUMES OR MIST	DASSAULT AVIATION	DATE: 9/06/2008 TIME: 16246.7 LD/CY:	DATE: TIME: 16546.7 LD/CY:
9/30/1976			INSPECT FUEL OVERFLOW DRAIN		
AD 76-19-05		TO PREVENT THE POSSIBLE INABILITY OF THE EMERGENCY FUEL SHUT OFF VALVES TO SHUT DOWN THE ENGINES	DASSAULT AVIATION	DATE: 5/27/1976 TIME: LD/CY:	DATE: TIME: LD/CY:
10/07/1976			CW/ SB 551		
AD 76-22-10		FAILURE OF THE MAIN LANDING GEAR DOWN LOCKS. P/N A23721, A23722 SERIAL NO. 1 THRU 807, 809 THRU 813,816,818,820	DASSAULT AVIATION	DATE: 4/15/1988 TIME: LD/CY:	DATE: TIME: LD/CY:
11/22/1976			CW/ SB 0529		
AD 77-02-08		NARCO MODEL ELT-10 EMERGENCY LOCATOR TRANSMITTER BATTERIES WITH A REPLACEMENT DATE PRIOR TO NOVEMBER 1977	NARCO	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
2/01/1977			N/A		
AD 77-07-02		TO PREVENT POSSIBLE HORIZONTAL STAB TRIM RUNAWAY	DASSAULT AVIATION	DATE: 6/22/2002 TIME: 11969.8 LD/CY:	DATE: TIME: LD/CY:
4/07/1977			VERIFIED PCW PER SB 568		
AD 78-07-06		TO PREVENT LOW CYCLE FATIGUE FAILURE OF COMPRESSOR DISCS SUSPECTED TO HAVE IMPROPER MATERIAL	GENERAL ELECTRIC	DATE: 10/10/1981 TIME: 1619.4 LD/CY:	DATE: TIME: LD/CY:
3/08/1978	LH		N/A		
AD 78-07-06		TO PREVENT LOW CYCLE FATIGUE FAILURE OF COMPRESSOR DISCS SUSPECTED TO HAVE IMPROPER MATERIAL	GENERAL ELECTRIC	DATE: 3/14/1980 TIME: LD/CY:	DATE: TIME: LD/CY:
3/08/1978	RH		N/A BY SERIAL NUMBER		
AD 78-20-12		REPLACE TIRES WITH P/N 00490 & SN 0677	FIRESTONE	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
10/05/1978			N/A		
AD 79-18-05		REPLACE LIS02 ELT BATTERIES: SUPERCEDES	ELT	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 79-18-05	R1	AD 79-05-02	N/A		
2/28/1980			N/A		
AD 79-21-02 b		TO PREVENT INADVERTENT OPENING OF THE PAX DOOR DUE TO INCOMPLETE MANUAL ENGAGEMENT IN CLOSING	DASSAULT AVIATION	DATE: 3/01/1979 TIME: LD/CY:	DATE: TIME: LD/CY:
11/12/1979			CW/ SB 604		
AD 79-21-02 c		TO PREVENT INADVERTENT OPENING OF THE PAX DOOR DUE TO INCOMPLETE MANUAL ENGAGEMENT IN CLOSING	DASSAULT AVIATION	DATE: 3/01/1979 TIME: LD/CY:	DATE: TIME: LD/CY:
11/12/1979			CW/ SB 615		

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N165FW

DIRECTIVE NUMBER AMENDMENT	REVISION LOCATION	DESCRIPTION	VENDOR METHOD	COMPLIANCE	NEXT DUE
AD 80-01-05	R1	TO PREVENT FAILURE TO OPEN OF THE FLIGHT CREW AND ATTENDANTS' SEAT BELTS, APPLICABLE TO PACIF.SCIEN. ROTARY BUCKLE	PACIFIC SCIENTIFIC	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 80-02-06		TO REDUCE THE POSSIBILITY OF FLEXIBLE LINE FAILURE IN THE ENGINE FIRE EXTINGUISHER SYSTEM	DASSAULT AVIATION C/W SB 632	DATE: 12/17/1979 TIME: 4604.7 LD/CY:	DATE: TIME: LD/CY:
AD 80-05-02		REPLACEMENT OF SEAT BELTS	HAMILL NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
2/27/1980					
AD 80-05-04		TO PREVENT INADVERTENT OPENING AND/OR FALSE LATCHING OF THE SEAT BELT/HARNES ASSEMBLY	EON CORPORATION NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
3/10/1980					
AD 80-07-13		PACIFIC INFLATABLES P/N 4000 AND 4000E SERIES FLOTATION DEVICES.	PACIFIC INFLATABLES COMPANY NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
4/07/1980					
AD 80-08-06	R1	TO PREVENT LOW CYCLE FATIGUE FAILURE OF 1ST STAGE TURBINE DISK P/N 5011T75P01	GENERAL ELECTRIC NA	DATE: 10/10/1981 TIME: 1619.4 LD/CY:	DATE: TIME: LD/CY:
5/30/1980	LH	& 2ND STAGE TURBINE DISK P/N 5011T76P01			
AD 80-08-06	R1	TO PREVENT LOW CYCLE FATIGUE FAILURE OF 1ST STAGE TURBINE DISK P/N 5011T75P01 & 2ND STAGE TURBINE DISK P/N 5011T76P01	GENERAL ELECTRIC N/A BY SERIAL NUMBER	DATE: 3/14/1980 TIME: LD/CY:	DATE: TIME: LD/CY:
5/30/1980	RH				
AD 80-18-05		REVISE CIRCUIT ON SPERRY STARS HSI RD044 TO PREVENT POSSIBLE ERRONEOUS PRESENTATION OF GLIDE SLOPE INFORMATION	SPERRY NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
9/29/1980					
AD 80-18-08		MODIFY EMERGENCY POWER SUPPLY PS-823 TO PREVENT LOSS OF EMERG ELECTRICAL POWR AND POSSIBLE CORROSIVE OR THERMAL	J.E.T. ELECTRONICS NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
8/28/1980					
AD 80-19-19		MODIFY DAC 2000, 7000 RNAV SYSTEMS	J.E.T. ELECTRONICS NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
4/24/1980					
AD 81-08-04		TO PREVENT THE REGULATOR INLET VALVE FROM CAUSING EITHER LEAKAGE OR POSITIVE PRESSURE WITHIN THE FACECONE	PURITAN NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
4/23/1981					
AD 81-21-05		REPLACEMENT OF ELT BATTERIES AIROTEX P/N 00-21-006	ARTEX NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
10/19/1981					
AD 82-18-09		REPL TYGOTHANE TUBING ON SINGL PT REFUEL	A.T.S. NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
10/04/1982					
AD 82-21-04		PS-835 EMERGENCY POWER SUPPLY INSTALLATIONS: TO PREVENT A FALSE INDICATION THAT EMERG POWER IS AVAILABLE	J.E.T. ELECTRONICS NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
10/21/1982					

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N165FW

DIRECTIVE NUMBER AMENDMENT	REVISION LOCATION	DESCRIPTION	VENDOR		COMPLIANCE	NEXT DUE
			METHOD			
AD 83-01-06		TO DETECT LIFE PRESERVERS AND FLOTATION DEVICES WHICH HAVE CO2 INFLATION VALVE MANIFOLDS THAT MAY OPERATE IMPROPERLY	SWITLIK		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: 6/06/1998 TIME: 7841.3 LD/CY:
2/28/1983			NA			
AD 83-02-03		TO PREVENT POTENTIAL FAILURE OF THE FIRE EXTINGUISHER TO OPERATE	DASSAULT AVIATION		DATE: 4/15/1988 TIME: LD/CY:	DATE: TIME: LD/CY:
2/09/1983			CMW SB 657			
AD 83-26-03		TREAD LOSS AND POSSIBLE SUBSEQUENT TIRE FAILURE	BF GOODRICH		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
12/23/1983			NA			
AD 84-02-08		TO PREVENT POSSIBLE USE OF IMPROPERLY CHARGED OXYGEN CYLINDERS, BLEED DOWN CYLINDERS & RECHARGE	SCOTT AVIATION		DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
2/09/1984			CMW			
AD 84-18-07		INSPECT FIRE EXTINGUISHER DISCHARGE CARTRIDGES	WALTER KIDDE		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
9/21/1984			NA			
AD 85-18-03		TO PREVENT FAILURE OF THE STAGE 1 TURBINE DISK, P/N 5011T75P01 WITH S/N THAT BEGIN WITH GATSRM	GENERAL ELECTRIC		DATE: 1/03/1983 TIME: 1957.5 LD/CY:	DATE: TIME: LD/CY:
11/15/1985			N/A PER SB CFA72-145			
AD 85-18-03		TO PREVENT FAILURE OF THE STAGE 1 TURBINE DISK, P/N 5011T75P01 WITH S/N THAT BEGIN WITH GATSRM	GENERAL ELECTRIC		DATE: 11/07/1997 TIME: LD/CY:	DATE: TIME: LD/CY:
11/15/1985	RH		NA			
AD 85-22-10		TO PREVENT INTERNAL GEAR SLIPPAGE THAT MAY RESULT IN ERRONEOUS DISPLAY	COLLINS		DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
12/31/1985			NA			
AD 85-26-01		TO PREVENT ANY POSSIBLE JAMMING AND FAILURE TO UNLOCK THE BELT	SECUR AIGLON		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
2/06/1986			NA			
AD 85-26-03		TO PREVENT THE BLOCKAGE OF OXYGEN FLOW DUE TO THE INCOMPLETELY DRILLED OXYGEN CONNECTORS	SCOTT AVIATION		DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
12/30/1985			NA			
AD 86-05-02		PRESSURE SENSITIVE ALTIMETERS	UNITED INSTRUMENT		DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
5/28/1986			NA			
AD 86-22-10		COLLINS DME-42 P/N 622-6263-002, DISTANCE MEASURING EQUIPMENT	COLLINS		DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
11/17/1986			NA			
AD 86-25-01		TO PREVENT DEVIATION OUTPUT SIGNAL OSCILLATION THAT MAY CAUSE UNDETECTED ERRONEOUS VOR & ILS DISPLAY	COLLINS		DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
1/06/1987			NA			
AD 87-04-19		REPLACEMENT OF EON C22 SAFETY BELT ASSEMBLIES INCORPORATING E8000 SEAT BUCKLE ASSEMBLIES	EON CORPORATION		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
3/18/1987			NA			

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N165TW

DIRECTIVE NUMBER AMENDMENT EFFECTIVE DATE	REVISION LOCATION	DESCRIPTION	VENDOR METHOD		COMPLIANCE	NEXT DUE
AD 87-06-09		REPLACEMENT OF MECHANICAL CIRCUIT BREAKERS INSTALLED AFTER 07/23/84	MECHANICAL PRODUCTS		DATE: 5/27/1988 TIME: 5682.6 LD/CY:	DATE: 5/27/1988 TIME: 5682.6 LD/CY:
4/17/1987			N/A			
AD 87-16-07		TO ELIMINATE ERRONEOUS DISPLAY OF THE ANGLE OR ATTACK FAST/SLOW PRESENTATION EFIS SYSTEM ONLY	SPERRY		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: 6/06/1998 TIME: 7841.3 LD/CY:
8/20/1987			NA			
AD 87-17-06		AM-SAFE INCORPORATED OCCUPANT RESTRAINT SYSTEM ASSEMBLIES	AM-SAFE INCORPORATED		DATE: 6/10/1998 TIME: LD/CY:	DATE: 6/10/1998 TIME: LD/CY:
9/22/1987			NA			
AD 87-20-05		REPLACEMENT OF DEFECTIVE LAP SEAT BELT ASSEMBLIES C22F PART NUMBER 1107177 ALL DASH NUMBERS	PACIFIC SCIENTIFIC		DATE: 1/05/1989 TIME: 5852.9 LD/CY:	DATE: 1/05/1989 TIME: 5852.9 LD/CY:
10/26/1987			N/A			
AD 88-13-06		TO PREVENT THE INABILITY TO EXTEND THE MILG DUE TO THE LATERAL DOOR REAR LOCK JAMMING	DASSAULT AVIATION		DATE: 9/12/1987 TIME: 5668.6 LD/CY:	DATE: 9/12/1987 TIME: 5668.6 LD/CY:
7/11/1988			C/W SB 502			
AD 89-02-05		TO ELIMINATE CYLINDERS WHICH MAY LEAK DUE TO CERTAIN MATERIAL USED IN THEIR FABRICATION; CYLINDER P/N 690104-205	BF GOODRICH		DATE: 6/10/1998 TIME: LD/CY:	DATE: 6/10/1998 TIME: LD/CY:
2/13/1989			NA			
AD 89-06-01		TO PREVENT THE IMPROPER FUNCTIONING OF THE CARBON DIOXIDE INFLATORS ON TSO-C13 LIFE PRESERVERS & TSO-C72 FLOTATION DEVC	SWITLIK		DATE: 6/10/1998 TIME: LD/CY:	DATE: 6/10/1998 TIME: LD/CY:
4/03/1989			NA			
AD 89-09-02		TO PREVENT THE POSSIBILITY OF THE SAFETY BELTS FROM BECOMING DIFFICULT TO RELEASE OR JAMMED WHEN ACTUATED THRU 90 DEGREES	DAVIS		DATE: 8/17/1989 TIME: 6102.9 LD/CY:	DATE: 8/17/1989 TIME: 6102.9 LD/CY:
5/24/1989			N/A			
AD 90-05-09		TO PREVENT NAVIGATIONAL ERRORS ON TRACOR TA-7800 OMEGAVLF NAVIGATIONAL SYSTEMS.	TRACOR		DATE: 6/10/1998 TIME: LD/CY:	DATE: 6/10/1998 TIME: LD/CY:
4/04/1990			NA			
AD 90-06-13		TO PREVENT ERRONEOUS ATTITUDE DISPLAY AND ERRATIC FUNCTION OF AUTOPILOT WITH HONEYWELL VERTICAL GYRO MODEL VG-14A	HONEYWELL, INC.		DATE: 6/10/1998 TIME: LD/CY:	DATE: 6/10/1998 TIME: LD/CY:
2/05/1990			NA			
AD 90-07-08	R1	TO PREVENT SMOKE, FIRE, AND POSSIBLE ELECTRICAL SHOCK OR ELECTROMAGNETIC INTERFERENCE TO FLIGHT SYSTEMS	S.E.L.A.		DATE: 6/27/1990 TIME: LD/CY:	DATE: 6/27/1990 TIME: LD/CY:
4/09/1990			DEACTIVATED			
AD 90-09-10		TO PREVENT POTENTIAL OVERHEATING OF TEXAS INSTRUMENT CIRCUIT BREAKERS MODELS 6TC6-7.5 & -10, 6TC20-7.5 & -10	TEXAS INSTRUMENT		DATE: 6/10/1998 TIME: LD/CY:	DATE: 6/10/1998 TIME: LD/CY:
5/30/1990			NA			
AD 91-10-01		PREVENT ALTITUDE DEVIATIONS WHICH COULD RESULT IN UNNECESSARY PILOT/CONTROLLER COMMUNICATION & CONTROLLER DISTRACTION	COLLINS		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: 6/06/1998 TIME: 7841.3 LD/CY:
3/10/1992			NA			
AD 91-10-05		TO PREVENT MALFUNCTIONING OF THE LANYARD RELEASE PIN THAT COULD PREVENT THE FLOW OF PASSENGER OXYGEN.	O2 CORPORATION		DATE: 5/29/1991 TIME: 6454.0 LD/CY:	DATE: 5/29/1991 TIME: 6454.0 LD/CY:
6/03/1991			N/A			

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N165TJW

DIRECTIVE NUMBER AMENDMENT EFFECTIVE DATE	REVISION LOCATION	D E S C R I P T I O N	V E N D E R		COMPLIANCE	NEXT DUE
			M E T H O D			
AD 91-15-15		PREVENT FAILURE OF A CREWMEMBER TO THE POUCH FROM THE BRACKET IN CASE OF A FIRE; MODEL 4568M37B-042N	E.I. DUPONT DE NEMOURS & CO.		DATE: 10/08/1991 TIME: 6490.9 LD/CY:	DATE: TIME: LD/CY:
AD 92-01-10		PREVENT IN-FLIGHT SEPARATION OF THE ENGINE COWLS	DASSAULT AVIATION		DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 92-16-15		PREVENT A LACK OF OXYGEN FLOW FROM PORTABLE EMERGENCY OXYGEN BOTTLES DUE DISCREPANT OXYGEN MASK PLUG IN	SCOTT AVIATION		DATE: 2/12/1993 TIME: 6693.7 LD/CY:	DATE: TIME: LD/CY:
AD 92-17-05		PREVENT REDUCED STRUCTURAL INTEGRITY	DASSAULT AVIATION		DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 93-04-02		PREVENT A MID AIR COLLISION OR NEAR MISS SITUATION CAUSED BY FAILURE OF MODE S TRANSPONDERS P/N CPN 622-9210-002	ROCKWELL INTERNATIONAL		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 93-07-05		PREVENT FAILURE OF THE PILOTS & COPILOT LAP BELTS DURING AIR TURBULENCE	AMI INDUSTRIES INC.		DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 93-12-04		PREVENT THE PRESENCE OF SMOKE IN THE COCKPIT	PRECISE FLIGHT INC.		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 93-14-12		PREVENT LEAKAGE OF THE PBE NECK SEAL, WHICH COULD COMPROMISE THE CREWS ABILITY TO FIGHT A FIRE; MODEL 4568M37B	ESSEX PB&R CORPORATION		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 93-23-01		PREVENT EXPLOSIONS OF GALLEY WATER HEATERS & COFFEE MAKERS	NORDSKOG INDUSTRIES, INC.		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 93-24-16		PREVENT FAILURE OF A PBE UNIT BECAUSE OF A DETERIORATED NECK SEAL; PROTECTIVE BREATHING EQUIP #119003, 119003-01	PURITAN BENNETT AERO SYSTEMS		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 94-01-04		PREVENT COLLISIONS CAUSED BY INCOMPATIBILITY BETWEEN TCAS II & TRAFFIC CONTROL; P/N 4066010-901-902-903	HONEYWELL		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 94-01-05		PREVENT COLLISIONS CAUSED BY INCOMPATIBILITY BETWEEN TCAS II & TRAFFIC CONTROL	ALLIED SIGNAL		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 94-01-06		PREVENT COLLISIONS CAUSED BY INCOMPATIBILITY BETWEEN TCAS II & TRAFFIC CONTROL	ROCKWELL INTERNATIONAL		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 94-02-02		PREVENT IMPROPER OPERATION OF DME P/N 622-4540-020, 622-4540-021, 622-4540-022, 622-4540-120, 622-4540-121	ROCKWELL INTERNATIONAL		DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N165TJW

DIRECTIVE NUMBER AMENDMENT	REVISION LOCATION	D E S C R I P T I O N	V E N D E R M E T H O D	COMPLIANCE	NEXT DUE
AD 94-06-04		PREVENT FAILURE OF THE PIN SECURING THE MASK SHELL TO THE FACE PIECE SERIES MF10-1J QUICK DONNING MASK	EROS NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 94-14-03		PREVENT EXPLOSIONS OF GALLEY WATER HEATERS & COFFEE MAKERS; NUPRO PRESS RELIEF VALVE P/N SS-2C4-65	NORDSKOG INDUSTRIES, INC. NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 94-19-06		PREVENT FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING INTO CREW OXYGEN MASKS	PURTAN BENNETT NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 94-21-06		PREVENT THE INABILITY OF PASSENGERS OR CREW TO EGRESS FROM THEIR SEATS DURING EMERGENCY SITUATION	PACIFIC SCIENTIFIC NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 95-01-01		RESPOND FAILURE OF THE TRANSPONDER TO RESPOND PROPERLY TO MODE S MODEL TRT 250 TRANSPONDERS	TERRA CORPORATION NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 95-22-01		TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK & POSSIBLE ELECTROMAGNETIC INTERFERENCE SUPERSEDES AD 90-14-06	AEROSPACE LIGHTING CORPORATION NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 95-24-10		TO PREVENT FAILURE OF THE MAIN LANDING GEAR TIRES DURING LANDING OPERATIONS	MICHELIN AIRCRAFT TIRE CORP. NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 95-25-08		TO PREVENT POSSIBLE EXPLOSION OF WATER HEATERS: ROYAL INVENTUM DR1 & DR6 SERIES GALLEY WATER HEATERS	ROYAL INVENTUM COMPANY NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 95-26-15	R1	TO ENSURE THAT THE FLIGHTCREW IS ADVISED OF POTENTIAL HAZARD WITH FAILURE OF AUDIO OUTPUT OF CAS-81 TCAS	ALLIED SIGNAL COMMERCIAL AVION NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 96-12-09		TO PREVENT INJURY TO HANDS DURING OPERATION OF THE PTC MODEL 950 SERIES PASSENGER SEATS	PTC SEATING PRODUCTS NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 96-21-13		TO PREVENT RELIANCE ON OR TO CORRECT THE CAUSE OF MISLEADING ROLL & PITCH INFORMATION	LITEF GMBH NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 96-25-12		TO PREVENT COMPRESSOR WHEEL RUPTURE LIFE LIMIT OF COMPRESSOR WHEEL P/N 162690-1, 165111-1, 167200-1	SUNDSTRAND AEROSPACE NA	DATE: 6/06/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 97-01-12		PREVENT FAILURE OF THE GPWS EQUIPMENT APPLIES TO CENTAURUS MODEL C3-100 GPWS	AIRTELL INTERNATIONAL INC. NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 97-04-15		TO PREVENT ELECTRICAL SHORTING OF THE PIN OF THE FIRE EXTINGUISHER BOTTLE CARTRIDGE & ITS MATING CONNECTOR	PACIFIC SCIENTIFIC COMPANY NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 97-04-15					

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N16STW

DIRECTIVE NUMBER AMENDMENT EFFECTIVE DATE	REVISION LOCATION	D E S C R I P T I O N	V E N D E R M E T H O D	COMPLIANCE	NEXT DUE
AD 97-05-03	R1	TO PREVENT DEVIATION OF THE INTENDED FLIGHT PATH DURING A NON-PRECISION APPROACHES	ALLIED SIGNAL AVIONICS NA	DATE: 6/06/1998 TIME: 7841.3 LD/CY:	DATE: TIME: LD/CY:
AD 97-11-10		TO PREVENT RESTRICTED OXYGEN FLOW MASKS P/N 174290-14, 174290-24 174290-34, 174290-44, 174290-54	PURITAN BENNETT AERO NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 97-13-10	LH	TO PREVENT AN OVERSPEED OF THE AFT FAN DISK	GENERAL ELECTRIC SB CF72-154	DATE: 3/13/1998 TIME: 6343.6 LD/CY:	DATE: TIME: LD/CY:
AD 97-13-10	RH	TO PREVENT AN OVERSPEED OF THE AFT FAN DISK	GENERAL ELECTRIC CW SB 72-154	DATE: 1/13/1999 TIME: 9226.6 LD/CY:	DATE: TIME: LD/CY:
AD 97-18-03		PREVENT FAILURE OF THE ULTRASONIC WELD ON THE CONE & SEAL ASSY OF OXYGEN MASK P/N 210543 & 210543-01	PURITAN BENNETT NA	DATE: 6/10/1998 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 97-25-08		TO PREVENT TURBINE TORQUE RING OR COMPRESSOR DRIVE SHAFT FAILURE	GENERAL ELECTRIC NA PER SB CFA72-155	DATE: 5/08/2000 TIME: 6922.7 LD/CY:	DATE: TIME: LD/CY:
AD 97-25-08	LH	TO PREVENT TURBINE TORQUE RING OR COMPRESSOR DRIVE SHAFT FAILURE	GENERAL ELECTRIC NA BY P/N-S/N	DATE: 3/19/1998 TIME: 8544.6 LD/CY:	DATE: TIME: LD/CY:
AD 98-08-20		TO PREVENT THE SERVO ACTUATOR ROLL PINS FROM BECOMING LOOSE	ALLIED SIGNAL AEROSPACE NA BY P/N S/N	DATE: 6/11/1998 TIME: 7843.3 LD/CY:	DATE: TIME: LD/CY:
AD 98-13-15		TO PREVENT LOSS OF THE WING-TO-FUSELAGE UPPER FAIRINGS	DASSAULT AVIATION INSPECTED	DATE: 9/06/2008 TIME: 16246.7 LD/CY:	DATE: 3/06/2009 TIME: 16546.7 LD/CY:
AD 98-14-03		TO PREVENT THE TRANSMISSION OF MISLEADING ENCODING ALTIMETER INFORMATION	ALLIED SIGNAL INC. NA PER P/N AND S/N INSTALLED	DATE: 4/18/1999 TIME: 8665.4 LD/CY:	DATE: TIME: LD/CY:
AD 98-23-06		TO PREVENT COMBUSTION LINER CRACKING AT MULTIPLE LOCATIONS	GENERAL ELECTRIC NA BY S/N INSTALLED	DATE: 11/13/1998 TIME: 6493.2 LD/CY:	DATE: TIME: LD/CY:
AD 98-23-06	LH	TO PREVENT COMBUSTION LINER CRACKING AT MULTIPLE LOCATIONS	GENERAL ELECTRIC NA BY S/N INSTALLED	DATE: 11/20/1998 TIME: 9226.6 LD/CY:	DATE: TIME: LD/CY:
AD 98-23-06	RH	TO PREVENT COMBUSTION LINER CRACKING AT MULTIPLE LOCATIONS	GENERAL ELECTRIC NA BY S/N & APPENDIX 1	DATE: 11/20/1998 TIME: 9226.6 LD/CY:	DATE: TIME: LD/CY:
AD 98-25-10	R1	TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM, MODELS CS, CT, FM, FN, GK, GL, JD, JE, JT, JU, MD, ME, MM, MN, NB, PM, PN, RG, RH	AIRCRAFT BELTS N/A EQUIPMENT NOT INSTALLED	DATE: 12/24/1999 TIME: 7848.5 LD/CY:	DATE: TIME: LD/CY:
AD 98-26-10		TO ENSURE THAT THE FLIGHT CREW IS AWARE OF THE EMERGENCY PROCEDURES ASSOCIATED WITH A FIRE	DASSAULT AVIATION CW - AFM INSERT	DATE: 1/25/1999 TIME: 8537.7 LD/CY:	DATE: TIME: LD/CY:

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

AIRWORTHINESS DIRECTIVE REPORT

FALCON 065

12/20/2008
N165TW

DIRECTIVE NUMBER AMENDMENT	REVISION LOCATION	D E S C R I P T I O N	V E N D E R M E T H O D	C O M P L I A N C E	N E X T D U E
AD 99-08-21		TO PREVENT REDUCED OXYGEN CONSUMPTION WHEN PASSENGERS ARE REQUIRED TO USE DEFECTIVE MASKS	PURITAN BENNETT	DATE: 6/17/1999 TIME: 8935.3 LD/CY:	DATE: TIME: LD/CY:
6/02/1999			N/A EQUIPMENT NOT INSTALLED		
AD 99-12-06		TO PREVENT VHF NAVIGATION RECEIVER INTERFERENCE FROM FREQUENCY MODULATION (FM) RADIO STATION BROADCAST	ALLIEDSIGNAL INC.	DATE: 8/31/1999 TIME: 9251.4 LD/CY:	DATE: TIME: LD/CY:
7/23/1999			N/A EQUIPMENT NOT INSTALLED		